


Henry Beaumont Herts




Hugh Tallant




1607 NEW AMSTERDAM THEATRE, NEW YORK.


COPYRIGHT 1905 BY DETRIT PUBLISHING CO.














SECTION










4

10 20 40




Who Were the Players?

- 42nd Street Development
- Disney Development
- Hardy Holzman Pfeiffer Associates
 - Theatre Projects Consultants
 - Jaffe Holden Acoustics
 - DeSimone Engineering
 - Edwards and Zuck Engineering
 - Building Conservation Associates
 - Two Twelve Harakawa Signage Design
- Tishman Construction

Design Challenges

- How do you increase the seat count from 1700 to 1800?
- What was the nature of the restoration?
- How do you account for different light levels?
- How do you provide for contemporary services?
- All for \$24M?








THE FOYER



BEFORE





AFTER


THE PROMENADE




BEFORE

































A B C D E F G H I J K L M

N O P Q R S T U V W X Y Z

A B C D E F G H I J K L M

N O P Q R S T U V W X Y Z

1 2 3 4 5 6 7 8 9 0

